Oil Field Environmental Incident Summary

Responsible Party: ONEOK Rockies Midstream **Well Operator:** ONEOK ROCKIES MIDSTREAM

Well Name: Keene Compressor station

Field Name: Well File #:

Date Incident: 4/17/2015 Time Incident: 15:00 Facility ID Number:

County: MCKENZIE Twp: 152 Rng: 96 Sec: 21 Qtr: NW NW

Location Description: Keene Compressor Station

1119239th Street NWKeeneND

Submitted By: Kimberly Rudningen Received By:

Contact Person: Kim Rudningen

2700 Lincoln Ave SE Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other 0.5 Gallons

Description of Other Released Contaminant:

natural gas condensate

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

There are no risks associated with this release

Areal Extent:

Release was completely contained within the secondary containment

Potential Environmental Impacts:

There are no expected impacts from this release.

Action Taken or Planned:

The impacted gravel will be removed and replaced with clean gravel.

Wastes Disposal Location: This will be removed to a certified landfill for disposal.

Agencies Involved:

Updates

Date: 4/20/2015 Status: Correspondence Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Email sent requesting more information regarding spill.

More followup is necessary depending on the additional information provided to the NDDoH.

Date: 4/20/2015 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, a very small amount of material was lost at a compressor facility.

Follow up with email.